



raiatea-yacht.com - info@raiatea-yacht.com

(+689) 87 29 06 09 - (+689) 87 27 79 38

Idylle 15.5 (15,50 m) - 1986

Layout :

- Length : 15,50 m (50' 9")
- Beam : 4.41 m (14'46")
- Draft : 1.90 m (6'23")
- Material : Fiberglass
- Rigging : Cutter
- Engine: Yanmar 4JH3-HTE, 98,7 HP



Price : 7,03 M XPF / 59 000 euros

EXCLUSIVITY R.Y.B!

Very spacious and bright sailboat.

Comfortable at sea. An opportunity to seize!

Interior fittings :

Sleeps 4 to 5 - 2 Double Cabins

- Large double owner's cabin
- Double Cabin
- 2 Heads
- Large L-shaped saloon that sleeps 1 adult + 1 child easily
- Fore double cabin transformed into a large storage and work area

Building and history

Fiberglass sailboat type IDYLLE 15.50 built in 1986 by BENETEAU shipyards, according to the designs of the architect German Frers.

She had a major refit in 2004.

The boat arrived in French Polynesia in March 2021.

Engine

Yanmar 4JH3-HTE engine, 98.7 HP (2004)

Tank capacity: 900 L / 238 gallons total, in 3 separate tanks

Cutter Rigging

Mainsail

Profurl furling genoa

Furling	jib	on	Profurl	forestay	(sail	in	bad
condition)							

Spinnaker

2018 sheets

Ground tackle

Main anchor: CQR anchor 34 kg/ 75 lbs with swivel + 50m of 10 mm chain + 20 m of rope

Secondary anchorage: Bruce anchor 20 kg / 44 lbs + 10 m chain 12 mm for the stern anchor

2 Dinghy anchors 3.5 kg, one with 1 m of chain

7 Large inflatable fenders + smaller fenders

Numerous mooring lines, most of them 18 mm

Comfort

Water capacity : 500L / 133 Gallon

Sigmar Marine combined electric and diesel water heater 80L / 21.1 Gallons

Watermaker 24V Schenker 100L / 26 Gallon / hour (WM energy recovery works on solar panels)

2 Heads with macerator pumps

Isotherm Cruise 130 (130 lt) front opening stainless steel refrigerator

Electrics

2 House batteries Aokly gel 120 Ah, Total 240 Ah (November 2023)

Battery monitor Victron BMV 700

Victron MultiPlus inverter and battery charger, 24V / 3000 VA / 70 Amp.

NEW: 05/2024

Victron Iso Transformer 3600W

Solar panels 1,4 kW, Victron chargers

Northern Lights generator, M673L.5, 6/5 kW

Electronics and navigation instruments

Raymarine Axiom 9 plotter (2018)

Raymarine plotter a6/7 (2014)

Raymarine Radar (2018)

Display plotter		integrated		into		the		main
Raymarine autopilot								SPX-30
Raymarine p70s display (2022)								
Raymarine 2021	ST4000+	autopilot	on	wheel,	new	divre	installed	in
Raymarine (2004)				ST4000+				display
Raymarine wind								
Raymarine depth								
AIS (2018)		Raymarine				AIS		700
Plastimo compass, liquid filled globe compass, installed in 2004								
Fixed DSC	VHF	Navicom		RT		450		-
Iridium phone				Go				satellite
SSB/HAM radio iCom M700 PRO, 2004 (antenna needs a small repair and reassembly in its new position)								
<u>Safety equipment</u>								
EPIRB EPRIB1		Ocean				Signal		rescueME
2 MOB1	Personal	AIS	beacons	MOB	Ocean	Signal		rescueME
Plastimo Transocean ISO 9650 liferaft, 4 people (revised in 2018)								
3 Fire extinguishers (tested and certified in 2020)								
4 Adult life jackets and 4 children life jackets								
<u>Tender</u>								
Tender 3D 2,4 m semi-rigid inflatable and aluminum bottom								
Mercury 4 stroke 6 HP outboard engine								

Miscellaneous

Washing
380

machine

Eudora

Babynova

Bathtub in the main head

Last bottom paint : 2020

Main strengths

Perfect combination of the strong hull of the 80s, with up to 6 cm (2 inch) thick fiberglass and the modern interior of a boat from the 2000s.

Deep cockpit for maximum security and comfort at sea.

Hard dodger and hard roof give excellent visibility and make her comfortable even in the rain.

ATTENTION :

The boat's inventories are based on the indications given by the owners and even if we do our best to see that they are in accordance with the reality, there might be some differences. The boat's and equipment's condition has to be checked jointly by the buyer and seller before the sale.

The respective responsibilities of both the seller and the buyer remain intact. In no case can Raiatea-yacht be held responsible for any defect on the boat.